

Leonard Park:

Secondary Source

4 Raw Wells- 2,4,6 and 7. Combine pre aeration and post aeration 2 & 4, 6 & 7. Contact chamber to wet well to distribution.

Blends with the surface water in the distribution. Around the exit of the park.

95% surface and 5% groundwater. This is a robust estimate, there are times when the wells are not in service.

See included flow sheets. Flows for the month of October 2016.

Aeration for Radon, disinfection and corrosion control.

No.

Each well head is enclosed in a box with a locked lid.

None. (unless the Diner is still on a well, also the medical buildings along Rte 172?)

Well information:

All active.

All have sampling spigots.

?

Bedrock wells

See attached sheets for next four bullets.